



What's the Uncertainty?



What's the Uncertainty?




What's the Uncertainty?




What's the Uncertainty?



What's the Uncertainty?



What's the Uncertainty?




Why Is There Uncertainty?



There is no
such thing as a
perfect
measurement.

Precision in Measurements

- Measurements must be reported to the correct number of digits.



Determine the “RULE” for measuring with the correct number of digits...

